

## Marden's Footpath Report January 2025

Due to vast amounts of rain, many of the footpaths have flooded and some of the Bridleways have been too muddy to ride along. There have been many reports of fallen trees blocking rights of way. Landowners were contacted and most of the debris has been cleared. Awaiting to hear how we proceed with installing the new stiles as there has been a change in the ordering procedure and a change in the installation process eg delivery. One landowner has agreed to install the kissing gates on his land.

Possible interest has been shown in the voluntary Footpath Officers Job and the prospective replacement has been invited to the next Council to find out more information. No response as yet.